APPROVED LAND CORNER	NORVELL TOWN	•	20	
P.A. 345 of 1990				#2035222
Chairman Lewis Culton		R RECORDATION CER		Liber 1542 Page 570 Page 1 of 2
or corners in 5-15-97	rining nequire	ment of Act 74, Mich.	P.A. 1970	Page 1 of 2 Jackson Co., NI
JACKSON (County)	ocated In:	Corner Code ##		Recorded
		m, r-	SURVEY &	05/15/97 11:30A Mindy Reilly
	T 4 S R 2 E		MONUMENTATION	Register of Deeds
	T R T R		APR 0 7 1998	
•	T R		ALK 0 1330	
2. Property Controlling S : in Section S	T		SECTION	
3. Miscellaneous S	ΓR			Stamp & File Number
Property in Sec. S	T R		Tregioter or becase	
1. Lot No, Recorded Pla	ıt .			
5. Private Claims			<u> </u>	E F G H I J K·L M
			2 6 5 5 - 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	├─ ┆─┼─┆─┼─┆─┼
				9 10 12
DEAN R. GUTEKUNST , in a field st	rvey on <u>October</u>	10, 1996		
to hereby certify that under requirements of Pin lines 1 and 2 above were in conformance	with regulations and	rules therefore as required	in the "1817	-16151413
current manual of survey instructions of the Management or by a decree of a Court of Laws	United States Departm and/or that the corner p	ent of the interior, Bureau of joints mentioned in lines 3, 4	Land 7 and 5 a 19 20	
above were in conformance with the rules of to court of Law; established, re-established,	the Michigan Board of L	and Surveyors or by a Decre	ee of a	21 - 22 - 23 - 24
expressed below:	monomora, to mo	institution, recovered, robi	10 30 29	28 27 26 25
4OTE: Not more than 4 corners, all in on this certificate.	the same town and	range, may be recorded	1 1 1 1	
on this certaicate.			12 -31 -32 13	33-34-35-36-
Description of original monument an			1;	
Original Government Post Hickory 8" S 76 E	set by Hervey 100 links	Parke, Deputy Sur	rveyor, February 18	24.
W. Oak 16" N 69½	W 72 links	(47.521)		
Perpetuation by B. F. La	Rue, November	15, 1884.		tones around at
B. Walnut 14" N 56 W. Oak 2" S 88		nks (70.785') nks (16.17')	corner. For of one witner	ound good traces
	- ·	nks (84.81')	or one wrone.	of Mickey
Continued on back.				The service of the se
Description of corner evidence found	d and/or mathod and	olied in restoring or react	oblishing corner	DEAN
Found broken FIRECLAY and			abhshing corner.	GUTEKUNST
Corner is 3' = East of ce			· 	No. 18658
center line of Owen Road	(gravel), with	no occupation Ea	st.	The state of the s
				The state of the s
Accepted FIRECLAY as a ca original corner, as remon	ireiul and lait lumented by LaF	niui perpetuation due in 1884.	of the position of	` the
	_			
Set a Standard Jackson Co buried on South side and	ounty Monument 3/4" iron buri	to replace the fixed on North side	reclay and left fir	eclay
), · 12011 0421	ed on North Side	or monument.	
		•		
Description of monument for corner a				
<u>K-9 T4S, R2E</u> Co	rner is a 4" d	iameter X 36" cond	crete monument with	a ½" X 36"
st	andard monumen	t for Jackson Cour	mped LS 18658, which ity.	h is a
N 50° W Southwes	t corner block	foundation house	# 10993 133.981	(one story addition
" P OT_M TORDIE O	ak (22 % 24 ")	159.25' 40d	& washer on North	side of 22" nat
N 75° W 17" Hick	ory	112.46' 40d	& washer on East s & washer on South	ide
**** N 79½0 W Utility			& washer on North	
		arker sign attache	ed 19.0'	
Λ Λ	1000			
gned by	alekune	Date l ia	y 1, 1997	
urveyor's Michigan License No	18658		ERRE ARRESTER BY MICHIGAN STATE SOAR	

K-9 T4S, R2E

A.) - P.A. - 74, recorded by Richard E. Gutekunst, RLS # 7863, dated December 28, 1972, in LCRC, Liber 1, Page 629, Jackson County Records.

Found fireclay with large top broken off. Set iron on South side of fireclay. Set capped iron on top of fireclay.

**** N 79½ E Telephone Pole 95.02'

*** S 14 E 13" Hickory 112.43'

* S 81 W Double Oak 159.2'

** N 40 W Foundation of two story house # 10993 121.12'

Approximately 4 East of center line of Lawrence Road, and 2' North of center line of Owen Road.

- P.A. - 74, recorded by Kenneth L. Suydam, RIS # 17636, dated March 22, 1978, in LCRC, Liber 3, Page 132, Jackson County Records.

iron pipe

** Southeast corner house N 40 W 121.12'

* Double Oak S 81 W 159.20'