	\overline{Z}	•		75 - S			
	N COUNTY	HER //	EAST 1 P	OST. SECTION 24			
P.A. 34	15 01 1000		NORVELL	•		#2044408 Liber 1549 Page 128	
Chairman Timony B. U.	13-9	<u> </u>	LAND COF	RNER RECORDATION CE	RTIFICATE	Page 1 of 1	
	28- 13-21,	_	Filing Req	uirement of Act 74, Mich	. P.A. 1970	Jackson Co., MI Recorded	
or corners in JACKSON	<u>'</u>			Carran Cada -tt	dievev &	08/15/97 10:48A	
(Cour		Loca	ated in:	Corner Code ##	ONUMENTATION	Mindy Reilly Register of Deeds	
. Public Land	Survey	т _	45 _R 2E	M-8		Meaterer or neare	
	•		R	4	APR 0 7 1998		
			R R				
. Property Co	•	S T _	R		SECTION		
in Section Miscellaneo			A B		Register of De	eds Stamp & File Number	
Property in			R		Tieglotei o. De		
. Lot No	, Reco	orded Plat _			АВО	DEFGHIJK'LM	
Private Clair	ms						
					3		
DEAN R. GU	itekunst		April 14	, 97 & June 9	77 <u>-</u>	-8101112	
DEAN R. GUTEKUNST in a field survey on							
lines 1 and 2 above were in conformance with regulations and rules therefore as required in the arrent manual of survey instructions of the United States Department of the Interior, Bureau of Land							
anagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 sove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a							
	stablished, re-es		-	re-monumented, recovered, fe	901 1 1	29 28 27 26 25	
		ers, all in th	ne same towi	n and range, may be record	ed 11		
on this	certificate.			·	1231	32 33 34 35 36	
·	•			and/or subsequent restorat	ion:		
Origina	l Governmen	nt Post s 491 v	set by Be	njamin Hough, Deputy links (32.67')	Surveyor, 1815-	1816.	
B. 0a	ik 24"	S 17 E	65 1	links (43.23')			
Hickory 12" S $33\frac{1}{2}$ E 81 links (53.46') witnes * Hickory 12" S 60 3/4 W $53\frac{1}{4}$ links (35.145') Bro						ound stake from remains of itnesses by 0. Curtis, 1852.	
						en Fireclay	
•• •						light traces of ent witnesses.	
Not rec	corded in P	. A. + 7	4.				
Description	of comer evide	ence found	and/or metho	od applied in restoring or re-	establishing corner:		
Found F pieces.				n backhoe excavation roken fireclay under			
Corner is 3' West of center line of Watkins Road (blacktop).							
No Occupation East or West at corner.							
				faithful perpetuati LaRue in 1884.	on of the positi	on of the	
	under monu			ment to replace fire es of fireclay burie		oken fireclay nd Southeast side of	
Description	of monument to	or corner ar	nd accessorie	es established to perpetuate	locating the position o	f the corner:	
<u>M-8</u>	T4S, R2E	bras		" diameter X 30" Cas mped IS 18658, which y.			
* S 65	° ₩ 32"	Hickory	35.6	9' Pole barn sp	ike and washer or	n North side.	
S 15° W 21" Hickory 83.95' Pole barn spike and washer on West side. N 70° E 15" Hickory 33.65' Pole barn spike and washer on North side.							
S 25° E 19" Osage Orange 61.51' Pole barn spike and washer on West side							
West	D 0001	F00 - t=:-			22	OF MICHIGAN	
Monum	ent box set	by the	Jackson (County Road Commissi	on.	DEAN	
- 4 (1//	com 1	State	Date	August 1, 1997	GUTEKUNST	
ned by	gan License No	186	558	Uate _	<u> </u>	No. 18658	