JACKSON COUNTY	1 (, , , , , , , , , , , , , , , , , , ,	•	· · · · · · · · · · · · · · · · · · ·	
APPROVED LAND CORNER P.A. 345 of 1990	NORTHEAST COP	-	5		
Chairman TIMOTHY & VANGIES					,
Date <u>/2-/2-96</u>	LAND CORNER	RECORDATION CERT	IFICATE		
Env garnara in	Filing Requirem	ent of Act 74, Mich. P.	.A. 1970	#2022463	
For corners in JACKSON	cated In:	Corner Code ##		Liber 1533	3 Page 343
(County)	Cateu III.	Contel Code 77		Pase 1 Jackson Co	of 2 a. Mi
Public Land Survey	_ 4 S _R 2 E	M-9		Recorded	34: /17
·	r R			12/12/96 (
	T R T R			Jerry McD: Register:	
				17% 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	A. B. M.
	Γ R				
	Г R Г R		Register of Dec	eds Stamp & File N	lumber
1 Topolity III dec. 0	·				
H. Lot No, Recorded Pla				DEFGHI	JKLM
5. Private Claims			2 6	-5-4-3-	_2_1_
			3		
DEAN R. GUTEKUNST	Oct	oher 10 96	4	- 8	1112
, in a field s	urvey onOct	19 , 19	, 5		
n lines 1 and 2 above were in conformance	e with regulations and r	ules therefore as required i	in the	-17-1-16-1-15-1	13-13-1
⇒urrent manual of survey instructions of the •Management or by a decree of a Court of Law			Land	-202122	23 24
above were in conformance with the rules of Dourt of Law; established, re-established	the Michigan Board of L	and Surveyors or by a Decre	ee of a		
⇒xpressed below:	i, monumented, re-mor	idinented, recovered, rour	10 30	_292827	2625
NOTE: Not more than 4 corners, all in	the same town and	range, may be recorded		 	
on this certificate.			12 31	-3233-34-	35 36
. Description of original monument a	nd accessories and/o	r subsequent restoration			
Original Government Pos	t set by Benjam	in Hough, Deputy	Surveyor, 1815	- 1816.	
Hickory 15" N $60\frac{1}{2}$	E 56 links	(36.96')			
W. Oak 11" S 3 Perpetuation by B. F. L	E 23 links	(1 5. 18 ') 14. 1884.	Found remains	of stake and	lone
* W. Oak 12" N 65	W 50 1 link	s (33.33')	witness (NE).		
** W. Oak 14" N 88	‡ W 44½ link	s (29.37')	under.		
Continued on back,					
•					
3. Description of corner evidence four	nd and/or method app	olied in restoring or reest	tablishing corner:		
Found FIRECLAY, from ab	ove information	, after excavatin	g box and iron.	ı	
Corner is approximately West or East.	in center line	of Watkins Road	(blacktop).	No occupation	on
Accepted FIRECLAY as a original corner, as rem			n of the position	on of the	
Set a Standard Jackson the North side of the m		over fireclay an	d left old iron	buried on	
				of the course	
Description of monument for corne					
		liameter X 36" con			36"
		aluminum cap sta t for Jackson Cou		MUTCH TR CHE	Mingles.
* N 65° W 26" W. C	ak 34.57'	40d & washer on	North side	THE TE OF	BUIGH BUIL
** N $88\frac{15}{2}$ W 32"W. 0)ak 30.35'	40d & washer on		11.50 .000	DEAN
N 55° E 21" Hick		40d & washer on 40d & washer on		*	R. 🛪
N 22° E 19" Walr	nut 71.70'	40d & washer on	East side	7 1	EKUNST 5
West Steel post	and survey mark	er sign attached		· · · · ·	18658
Replaced monument bo	ox oyer monument			MAKRED.	WALL SURFIELD
No. 11	11_A		November 30,	1996	TARD
Signed by	Klipeinel	Date		-//-	

18658

Surveyor's Michigan License No.

è

Continued,

. . .

M-9 T4S, R2E

A.) - Perpetuation by Richard E. Gutekunst, RLS #7863, dated May 8, 1970.

Found large top Fireclay, with top broken off, 3.0' below blacktop surface. Set iron on top of Fireclay to surface.

*	N	65 W	24"	W. Oak	34.591
**	N	88 1 W		W. Oak	30.35
	N	60 <u>‡</u> E	15"	Hickory	36.96
	S	18 W	15"	W. Oak	69.81
	N	22 E	8"	Walnut	71.7'
	N	55 E		Hickory	35.4

- P. A. - 74, recorded by Richard E. Gutekunst, RIS # 7863, dated February 16, 1972, in ICRC, Liber 1, Page 99, Jackson County Records.

Shows same above information as 1970.

- Information from the Jackson County Road Commission shows same witnesses as 1970 information above.

Monument box set 1979.