P.A. 343 OI 1990	CR TOWNSHIP	LIBER 1482 PAGE 647
Chairman 12-6 Ren Enger LAND	CORNER RECORDATION CERTIFICATE	
Date 12-30-94 Filing F	Requirement of Act 74, Mich. P.A. 1970	STATE OF MICHIGAN
JACKSON Located In:	Comer Code ≠	JACKSON COUNTY
(County)	Some Sode 44	RECORDED
1. Public Land Survey  T 4 8 R 2 T R	— ·—	17 AUG 95 9:59 A.M.
T R _		GERALD J. MCDEVITT
2. Property Controlling S T R _		REGISTER OF DEEDS
in Section S T R _		
3. Miscellaneous S T R _		gister of Deeds Stamp & File Number
Property in Sec. S T R _		
4. Lot No, Recorded Plat		- ABCDEFGHIJKLM
5. Private Claims		2 6 5 4 3 2 1
		3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
TO A STATE OF THE PARTY OF THE	August 35 94	4 7 8 9 10 11 12
DEAN R. GUTEKUNST, in a field survey on do hereby certify that under requirements of P.A. 74, Michi	and P.A. of 1970, the corner points mentioned	5
in lines 1 and 2 above were in conformance with regula	tions and rules therefore as required in the	6 18 17 16 15 14 13
current manual of survey instructions of the United State Management or by a decree of a Court of Law and/or that the	s Department of the Interior, Bureau of Land he corner points mentioned in lines 3, 4 and 5	8 19 20 21 22 23 24
above were in conformance with the rules of the Michigan	Board of Land Surveyors or by a Decree of a	9
Court of Law; established, re-established, monument expressed below:	ed, re-monumented, recovered, found as	10
NOTE: Not more than 4 corners, all in the same	town and range, may be recorded	11
on this certificate.		12 32 33 34 35 36
A. Description of original monument and accesso	ries and/or subsequent restoration:	13
Original Government Post set by W. Oak 10" N 40½ E 89 W. Oak 10" S 25 E 85 Perpetuation by H. F. Bean, July W. Oak 26" S 77½ E 109 W. Oak 26" N 39 E 80 Post standing with brick around witness and remains of other.  Not recorded in P. A. 74	9 links (58.74') 1 links ( 52.8') y 1886 5 links (69.3') 3 links (58.08') stump 1916	71.45 intersect West boundary 145 links (95.7') South of post. Fireclay Post (3'Dia. x 24")
B. Description of corner evidence found and/or m	nethod applied in restoring or reestablishing	g corner:
Found FIRECLAY, 4' below gravel Backhoe excavation of 6' x 6' x Found a ½" rod 6" below gravel	surface of Grover Road, with 4 deep area to find firecday.	4-5/8" rods around.
Fireclay has previously (1898 & Standard corner 145 links (95.7	') North , and need not be amen	nded.
Accepted FIRECLAY as a careful corner, as remonumented by Bean County Monument and left firecl surface of Grover Road.	in 1886. Replaced firecla	ay with a Standard Jackson
C. Description of monument for corner and acces  A-7 T4S, R2W Corner is steel rod	sories established to perpetuate locating t a 4" diameter X 36" concrete a and an aluminum cap stamped Is	monument with a ½" X 36"
	monument for Jackson County.	AND MICHEL
S 60° E 17" Oak 73.25'	40d & washer on North side	THE STATE OF THE S
S 10° E 15" Oak 123.34'	40d & washer on West side 40d & washer on Northeast	DEAN
	.15' no nail - center of tr	
North Found $\frac{1}{2}$ " iron in m		No. 18658
West Steel post with survey m	arker sign attached 30.0 ±	The second second
1 2.1	1 1	December 29, 1994
Signed by Neam Con	lekend Date	December 29, 1994""

18658

Surveyor's Michigan License No.