JACKSON COUNTY APPROVED LAND CORNER LIBER 1451 PAGE 196 P.A. 345 of 1990 NE CORNER OF SECTION 2, HANOVER TWP. Chairman Nemb Date Dec. 20, 1994 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 For corners in STATE OF MICHIGAN Jackson JACKSON COUNTY Located In: Corner Code ## (County) RECORDED T 4S R 2W 1. Public Land Survey 30 DEC 94 11:23 A.M. SURVEY & T _____ R ____ __ R __ REMONUMENTATION GERALD J. MODEVITT T R REGISTER OF DEEDS ___ T ___ _ R _ 2. Property Controlling MAY 0 3 1995 ____ T ____ R __ S_ in Section S ____ T ___ _ R __ 3. Miscellaneous Register of Deeds Stamp & File Number Property in Sec. COMMISSION ___ , Recorded Plat _____ 4. Lot No. ___ B C D E F G 5. Private Claims _ IArden S. Pierson PS in a field survey on December 2 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 expressed below: 11 NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: Wescription of original monument and accessories and/or subsequent restoration:

K-1 - Original survey by Robert Clark Jr. DS in 1825 - 82.54 chains intersect N. Bdy 2.14 chains E. of post, set post for cor Sec 1&2 - 10" W.Oak -N53°E- 4½ (links) 8" W.Oak -S61°E- .39 (links)

County Surveyor records show in a survey by H.F. Bean dated July 30- October 6, 1886, that he set a fireclay post as the corner With Witnesses: 34" W. Oak -S20°E- 90 (links)(59.40') 10" Br. Oak -S53°W- 4 1/2 (links)(2.97') \$ 2.00 REMONUMENTATION *(SEE BACK OF SHEET) \$ 9.00 CORNER REHONUMENTATION B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Section 2, Hanover Township K-1 - Found (2) pipes 2.45' North-South, closing distance from standard corner fall inside a 36" Oak stump - Accepted iron pipe with RLS #7863 as the position of the amended corner, the standard corner is N89°30'24"W 142.58' from this corner and the other pipe is N01°08'59"W 2.45' from this corner. Set Standard Jackson County Monument. C. Description of monument for corner and accessories established to perpetuate locating the position

K-1 (NE corner of Section 2)

Jackson County Monument

(STANDARD CORNER IS WEST 142.58')

Witness sign post set -South- 3.0'

"120220 E cide 7" Cherry -N40°E- 6.28' MAGISTA DE LAND Nail & tag #13039 E. side 7" Cherry -N40°E- 6.28'
Nail & tag #13039 SE side 23" Cherry -N70°E- 19.35'
Nail & tag #13039 SW side 7"& 14" Cherry -S47°E- 17.36' Nail & tag #13039 E. side 12" Cherry -S04°E- 18.52' Face of 40" Oak stump - West - 0.9' *Standard Jackson County Monument is a 1/2" iron rod 36" long with a Jackson County Remonumentation disk encased in a 4" concrete cylinder. December 6, 1994 elde A. Lieu _____ Date ___

13039

Surveyor's Michigan License No. ___

NE CORNER OF SECTION 2, HANOVER TOWNSHIP

Certification by H.F. Bean (page 620, GLO Notes) "post set are fireclay, three inches in diameter and two feet long"

JACKSON COUNTY ROAD COMMISSION RECORDS

West - fireclay 142.52'
S'ly nail in E. side 36" Oak - 2.51'
W'ly nail in N. side 36" Oak - 2.10'
S20°E - 14" Oak 43.80'
S85°E - 2" steel corner post -30.15'
East - 12" Oak - 44.88'
N80°W - 36" Oak - 51.30'