LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970 For Corners In: KALKASKA Located In Corner Code # (County) MAN F 1 2000 1. Public Land Survey T 25N R 6W SECTION 2. Property Controlling in Section 3. Miscellaneous Property in Section Register of Deeds Stamp & File Number 4. Lot No: Recorded Plat: 5. Private Claims: I, Craig W. McVean, in a field survey on Sept. 20, 1999 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may 10 be recorded on this certificate. 11 12 13 A. Description of original monument and accessories and/or subsequent restoration: C4-GLO-Set post- G. Cannon-1852 -LCRC L. 2,P. 226-C.F.Roser-1981-Set 5/8" X 36" rebar 33' east Sp. Pine 6" N44E 32 L., Sp. Pine 8" S36°W 14 L. of fnd. conc. ROW mon. per Richards. 12" J. Pine N55°E 65.44', -E. Mosher-1884-Rd, Survey 14" J. Pine S53°E 56.81', 8" J. Pine S55°W 61.21', 12" Cherry(Clp.) -W.S. Merrill-Dist. N & S-1911 N62°W 81.89', Added Cedar Post next to ROW Mon. -Fargo Eng.- Caukins-1912 -Fnd. GLO Sp. Pine Stp. -Set Iron & -DNR survey proj # 31-93113-1982 Crockery Mon.- W. Pine 14" \$74°30'W 117.5L. -Rec. Sur.-L.1, P.783-785-1975- W. Richards- Tuller's ½" Iron Rod found. B. Description of corner evidence found and/or method applies in restoring or re-establishing corner: C4- 1/4 corner common to Sections 7 & 8- Fnd. Capped 5/8" rebar per record LCRC by Roser. Removed capped 5/8 X 36" rebar and dug down 1.5' & found ½" X 18" rebar w/ wood stake under Roser position. Irons in CL of N-S gravel road – no evidence of Fargo monument found. Irons fits Fargo distance N&S. Rebars accepted as the best available evidence of the position of the original C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: C-4 - Replaced Rebarsw/ 3" Kalkaska Co. Remon. Brass cap on 5/8" X 34" Rebar, add coffee can w/ conc. around B.C. - down 0.6' West 32.99' to conc. mon. w/ 1/2" iron & cedar post w/ loc.tag S68°W 51.39' to set N&T in S. side 8" J. Pine scribed 'XBT' N68°W 83.72' to set N&T in N. side 11" Cherry in clp. (CFR) CRAIG W. N42°W 90.36' to set N&T in SW side 8" R. Pine McVEAN N80°E 37.83' to set N&T in S side 5" J. Pine scribed 'XBT' PROFESSIONAL SURVEYOR S48°W 61,23' to set N&T in SE side 12" J. Pine (CFR) No. 39088 Signed by: Surveyor's Michigan License Mo .: 39088

Date .

P.A. 345 1990 Kalkaska County

Ratified by Peer Group

LB: 6 PG: 54