Cons. 4047 4/56

## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T 3 NR 6 W

		W. C.		
		Kalkaska		COUNTY
DESCRIPTION OF CORNE	ER 1/4 corner	common to Sect	ions 2	1 and 22
DESCRIPTION OF CORNE	R MONUMENT_	I" pipe with 4"	_praes	_cap
WITNESSES TO CORNER	\			
	15" B. Oa	k - N59E	_	87½ links
	8" <b>J.</b> Pi	ne - N85W		42 links
				•

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a partial resurvey of this township. Corner was previously restored by Marcus Schaaf, Registered Land Surveyor, in 1940, from the sites of the probable government BTs.

Corner was placed and witnessed June 6, 1955.

SURVEYORS SEAL

SIGNED LEMENT SURVEYOR