83

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 25 N. S., R. 6 W.	A-4; A-5; C-3; D-3
2. PROPERTY CONTROLLING IN SECTION	,T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on January 23, 19 81, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. Continued

C-3

Fd. Rd.Conc. Mon. added cedar post w/loc tag
24" W. Pine N35°E 35.00
8" Cedar S58°E 27.0
In ℄ B.T. Rd. W & S
(Ctr. gravel rd. to east in curve)N 50'±

D-3

Fd. 3/4" pipe
6" P Pine N07°W 62.84
10" Tri. Maple S22°W 70.84
Fd. sq. conc. mon. N05°E 33.00'
Fd. well pt. S37°46'W 8.0'
Set ced. post South 40'
24" W. Pine stump S15°E 54.2'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

A-4 Fd. 3/4" Fargo pipe (1912) as recovered by Richards & Assoc. in 1975. Fargo notes indicate they had an original Govt. Corner here.

A-5 Recovered Fargo 1" pipe for SW corner of Sec. 7. Fargo (1912)notes indicate they had an original Govt. corner here.

C-3 Fd. & accepted round concrete monument as recovered by Richards & Assoc. in 1975; see Cert. of Survey, Liber 2, Pgs. 267 to 270.

D-3 Fd. 3/4" pipe (Richards call it a 1/2" pipe) accepted for N1/4 cor. Sec.8. Corner is 7'-N of E-W sand & gravel road. A former Conservation Dept. Monument (M. Schaaf 1943) N39° 52'W has been graded out. (N39°52'W, 8.0').

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-4

Fd. 3/4" pipe, replaced w/D.N.R. Mon. & Ced Post
*6" Maple N10°E 8.17
*8" Maple S79°E 23.44
*14" Cedar S80°W 21.19
*=Old Wits

A-5

Fd. 1" pipe (Fargo)& added D.N.R. Mon. & set ced. post
9" Cedar N10°E 18.9
9" Spruce N80°W 27.5
10" Tamarack S25°W 23.9

SIGNED BY Carl F. Roser 3-11-81 DATE _____

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 (SEAL) REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

GARFIELD TOWNSHIP (Central Part)
KALKASKA COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET