84

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 25 N., R. 6 W.	E-3; E-5; D-5
2. PROPERTY CONTROLLING IN SECTION	T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on January 23, 1981, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

B. Continued: (D-5)
computed position (no point set) for S1/4 S-8 midway & on line between SE & SW of S-8. This comp. point would be 16.4'-E & 0.8'-N of Fargo pipe; we could not accept Parker's comp. position either.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

E-3 Fd. Dept. Monument (M. Schaaf 1940-K. Ostling 1956-Richards & Assoc. 1975) with Fargo 1" pipe (1912) along side same. Good original Govt. corner.

E-5 Fd. Dept. Monument as established by Marcus Schaaf in 1941 from original Govt. line tree east. Corner monumented by Dept. in 1955 and since used by others.

D-5 Fd. & accepted Fargo Eng. 3/4" pipe (1912) as recovered & accepted by Richards & Assoc. Cert. of Survey, dated Dec. 17, 1975; Job No. 7439; Liber 2, Pgs. 267-270. Fargo's notes indicate they had an original Govt. Corner here (S1/4 Sec. 8). A Conservation Dept. Mon. (by M. Schaaf in 1941) S45°E 16.8' was removed as we could not accept this corner. Note: in 1970 N. Parker, R.L.S., Grayling, made a survey for the S1/2-NE1/4 of S-8 and used a

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-3

Fd. D.N.R. Mon. added ced. post

*7" R. Pine	N 53°E	28.71
*20" Oak	S38°E	41.00
*20" R.Pine	N82°W	55.00

Ctr. E-W Gravel Rd. N 305'±

* = Old Wits

E-5

Fd. D.N.R. Mon. & added Cedar post

*10" J. Pine	N28°E	8.91
*9" J. Pine	S59°W	20.48
*10" J. Pine	N73°W	29.82
N-S trail rd.	East	40'±
Winding trail rd. westerly	South	22'±

* = Old Wits

D-5

Fd. 3/4" Fargo pipe-Replaced w/ 5/8" x 36" rerod w/plastic cap & set ced. post w/Loc tag

*9" J. Pine	N68°E	49.62
*13" J. Pine	N55°W	20.08
*5" J. Pine	S40°W	22.75

* = R.F.R. Wits from 1978 Corner Record

SIGNED BY Carl F. Roser DATE 3-16-81

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN — CARL F. ROSER (SEAL) LAND SURVEYOR No. 12028 — REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

GARFIELD TOWNSHIP (Central Part)
KALKASKA COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET