85

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 25 N. S., R. 6 E. W.	C-4; C-5; D-4
2. PROPERTY CONTROLLING IN SECTION 8	,T. 25 N. S., R. 6 E. W.	11
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on January 23, 19 81, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

B. Continued:
D-4: 8 (Set in error-See S 1/4 Sec. 8) is N64°56'E, 8.21'.
11: Established ctr. of SW 1/4 of Sec. 8 per std. B.L.M. instructions.

C. Continued:

11
Set 5/8" x 36" rerod w/RLS cap & ced. post w/Loc tag

9" J. Pine	N09°W	114.4'
6" J. Pine	Due E	73.7'
6" J. Pine	S01°E	128.3'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

C-4 Drove 5/8" x 36" re-rod, 33.00'-E of fd. conc. ROW Monument & on line across W1/4 Cor. of Sec. 7 & said fd. Conc. ROW Monument. Corner fits Richards & Assoc. Cert. Survey of Secs. 7 & 8.

C-5 Restored Sec. corner common to Sec's. 7-8-17-18 per Richards & Assoc. Cert. of Survey, dated Dec. 17, 1975; Job No. 7439; Liber 2, Pgs. 267 to 270. Both Richards Corner (fd. 1 1/4" pipe-probably by Fargo in 1912) and Dept. of Conservation Corner (by M. Schaaf in 1941) N8°34'E 4.88' from Richards fd. corner had been graded out by road improvements. We were able to restore & accept Richards fd. corner from his Sur. data & two of his Wits.

D-4 Established ctr. of S-8 at intersection of 1/4 lines. R.L.S., Norm Parker's ctr. of Sec.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-4

Set 5/8" x 36" rerod w/R.L.S. cap		
12" J.Pine	N55°E	65.44
14" J. Pine	S53°E	56.81
8" J. Pine	S55°W	61.21
12" Cherry (cluster)	N62°W	81.89
fd. conc. ROW Mon.	W	33.00
Set ced. post w/Loc tag	W	33'
℄ N.S. Gravel Rd. is E.		1'±

C-5

Drove 1 1/4" x 18" rod (buried)		
8" R. Pine	N38°W	87.6
12" R. Pine	S86°W	67.1
*24" R. Pine (dead)	N44°W	77.1
P. Pole	S28°W	84.74
In ctr. N-S gravel Rd.		
Set ced. post w/Loc Tag	E	33'

D-4

Drove 5/8" x 36" rerod w/RLS cap & set ced. post w/Loc tag		
8" J. Pine	S60°E	124.5
*16" Dead J.Pine	S14°W	71.8
10" Cherry	S40°W	60.9
fd. Parker 1/2" pipe	N64°56'E	8.21'

* Parkers Old Wit

SIGNED BY Carl F. Roser 3-16-81 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN
CARL F. ROSER
LAND SURVEYOR
No. 12028
REGISTERED LAND SURVEYOR
(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

GARFIELD TOWNSHIP (Central Part)
KALKASKA COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET