

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES


LAND CORNER RECORD

KALMASKA COUNTY  
T 25 N R 7 W

DESCRIPTION OF CORNER N 1/4 corner section 32  
CORNER MONUMENT Added DNR Monument w/Cedar Guard Post  
DATE MONUMENT PLACED AND WITNESSED 1-12-72

WITNESSES TO CORNER.....

<u>4" R. Pine</u>	<u>N 57 E</u>	<u>70.7'</u>
<u>8" R. Pine</u>	<u>S 81 E</u>	<u>94.0'</u>
<u>5" R. Pine</u>	<u>S 41 W</u>	<u>30.2'</u>




AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

**Recovered "Fargo" corner, 1912, 3/4" Pipe.**



SURVEYOR'S SEAL

*Carl F. Roser*

SIGNED

DATE

1-19-72

REGISTERED LAND SURVEYOR #12028

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing