	SHAWEY&	
RET	- Stor Substanting	1

## LAND CORNER RECORDATION CERTIFICATE

MAR / Tonne

For corners in	Filing Requir	ement of Act 74, Mich. P.A. 1	970 WEST.	L A ZUUU
		1	المراجعة المنتاء	Transmission as a second miles of
KALKASKA (County)	Located in:	Corner Code #		TION
1999 REMONUMENTATION  1. Public Land Survey	T <u>25N</u> R <u>8W</u> T <u>R</u> T_R			3020137
2. Property Controlling Sin Section S 3. Miscellaneous S Property in Sec. S	TR TR TR TR	Kalkaska County Jo	-	Page: 1 of 1 02/04/2000 03:18P REMON LB: E PG: 83 Stamp & File Number
4. Lot No, Recorded Pl	lat			
			ABCDEF	G H I J K L I
I, EUGENE FARRIER hereby state that under requirements mentioned in lines 1 and 2 above were required in the current manual of survey Bureau of Land Management or by a mentioned in lines 3, 4 and 5 above we Land Surveyors or by a Decree of a recovered, found as expressed below:  NOTE: Not more than 2 comers, all in this certificate.  A. Description of original monumen J-7: 1/4 Cor. Common to Sec. 14 & 1852, G.L.O. Resurvey, by V.W. Caukin S41°E, 22 Lks (14.52°) 1918, Survey, by W.S. Merrill (Co. Surveyor), visited 1973, LCRC & Survey, by D.R. Verba, (Lwitness ties found as per 1922 Merrill not tag SW side 8" Hemlock, Az. 152°, 18.1	in a field survey of P.A. 74, Michigan is in conformance with reinstructions of the United decree of a Court of Levere in conformance with the court of Lew; establish the same town and range at and accessories and/of 23, T25N-R8W, Spring (Deputy Surveyor) Co. Survey Bk 24, Pg d corner, no accessories. CRC recorded in Liber 1, ptes, set nail w/ RLS tag.	y on November 2 , 19 99 do P.A. of 1970, the corner points regulations and rules therefore as States Department of the Interior, w and for that the corner points the rules of the Michigan Board of red, re-established, monumented, may be recorded  or subsequent restoration: pried Township rvey Notes Pg 283, set corner, Her g 1, set corner (M.P.O.L.), Pine stun Pg. 270; Survey recorded in Liber 1	np 38", N40°W, 15 1/2 Lk . Pgs. 288 & 289), set 5/8	(17.82'); Hemlock 8", s (10.23')
Maple, Az. 357°, 31.04° 1993, LCRC & Survey, by J.D. Geers, (Loby Verba (1973), same witnesses				
B. Description of corner evidence found <u>1-7: 1/4 Car. Common to Sec. 14 &amp; Found &amp; accepted 5/8" rerod at West ed.</u> N82°E, 30.15', 1" iron pipe 1.5' +/- abc \$73°E, 22.22', 10" W. Birch \$55°W, 28.53', 6" Twin Maple N55°W, 26.38", 6" W. Pine N50°E, 6.97', 5" Maple in clump No G.L.O. witnesses were found.	23. T25N-R8W. Spring ge of swamp line.	Ratified by Peer ( P.A. 345 - 1990) Chairman	Kalkaska County	
C. Description of monument for corner J-7: 1/4 Car. Common to Sec. 14 & Found & accepted 5/8" rerod at West ed; N82°E, 30.15', 1" iron pipe 1.5' +/- abox 573°E, 22.22', 10" W. Birch \$55°W, 28.63', 6" Twin Maple N55°W, 26.38', 6" W. Pine N50°E, 6.97', 5" Maple in clump Kalkaska County Peer Group accepted the	23. T25N-R8W. Spring ge of swamp line. Added a ove ground e above monument as a c	ed to perpetuate locating the position of the	on of the corner:	EUGENE D. FARRIER ROPESSIONAL SURVEYOR No. 24594
Signed by Signed by Michigan License No. 24594	ano	Date	04-00	Surveyor's