MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T26 NR 5 W

			, -	Kalka	ska	_ COUNTY
DESCRIPTION	OF	CORNER	1/4 corner c	ommon to Se	ctions 19 &	<u>5</u> 0
DESCRIPTION	OF	CORNER	MONUMENT_1"	pipe with	4" brass cap	 .
WITTNESSES	то	CORNER	6" Cedar -	N5ir -	18 Links	
			5" Cedar -	- N31W	25 links	
			· ·		,	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a partial resurvey of this township. Both original BT stumps in place, with evidence of face on one. Found very old stake point in muck below surface, while searching for corner.

Corner was placed and witnessed Nov. 14, 1955.

SURVEYORS SEAL

SIGNED Silly & Buckles
REGISTERED LAND SURVEYOR

DATE 3/12/56_