LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

SHIFVEY &

| Kalkaska | Located In: | Corner Code # | j | RED AND AND STATE |
|--|---|--|---|---|
| (County) | Located III. | Comer Code # | | MAR () 1 2000 |
| Public Land Survey Miscellaneous | T <u>25N</u> R T <u>25N</u> R T <u>26N</u> R T <u>26N</u> R S T R | 7W M-1 6W A-13 | | SECTION |
| Property in Sec. | s rR_ | | | 4,5 |
| 3. Lot No , Rec | orded Plat | | Ĺ | Register of Deeds Stamp & File Number |
| 4. Private Claims | | | | A B C D E F G H I J K L H |
| under requirements of P.A. 7 lines 1 and 2 above were in cin the current manual of survinterior, Bureau of Land Mancorner points mentioned in linthe Michigan Board of Land 8 | a field survey on Nov. 10 4, Michigan P.A. of 1970, the conformance with regulations a ey instructions of the United Stagement or by a decree of a Cales 3, 4 and 5 above were in conformation or by a Decree of a 6, recovered, found as expressed | corner points mentioned in nd rules therefore as required ates Department of the ourt of Law and /or that the onformance with the rules of Court of Law; established, | • | 1 2 6 3 4 3 2 1 1 2 3 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 |
| NOTE: Not more than certificate. | 2 corners, all in the same | town and range, may be i | recorded on this | 9 |
| , | | t . | | 10 30 29 28 27 26 25 11 31 32 33 34 35 36 138 - |
| A. Description of original monument and accessories and/or subsequent restoration: | | | | |
| - Fargo Eng. with U.S. to Cherry 10" Elm 8" N37 - W. S. Merril | S41°E 24 L. N53°E 68 L 1912 – Fnd. pt. of old sta opo. Set iron & Crockery M S12°W 0.76 3/4 Ch. 7.5°E 0.59 1/2 Ch. I – 1928 - Survey Sec. 36, V CSR L. 1,P. 55 | Stm ke-Cks well wid /lon. W,I - Richa Mon. | 5 L. Stm 10 L. wide S 10 L. wide SW. W. le SE. Cor. at inter. o E,N. & S. rds, Findorff & Richa 1968. Sur. L.3, P.102 – Fnd | 70 L. STM 30 L. of wire fences |
| B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: | | | | |
| A-1, M-1, - A-13 & M-13 Twp. Corner common to Sec. 6, T25N, R6W, Sec. 1, T25N, R7W, Sec. 31, T26N, R6W & Sec. 36, T26N, R7W - FND. conc. Mon. with 1/2" iron rod at intersection of fence remains N, S, E & W on S. side of rotted off anchor post. Measure West 44' (66' - GLO) to W. Bank of Stream - S. Measure E 58'± 3' to edge of swamp and bottom of bank. Fits position as described by Schaaf. Dug around fence Cor. but found no evidence of Fargo Pipe or Crockery. Fits Fargo distance E, W & S. Fits Merrill distance W. New Deer fence corner W & S is 1.5' N. & 1.7' E. Conc. Monument accepted as the best available evidence of the position of the original corner. | | | | |
| C. Description of mor | nument for corner and acco | essories established to perp | petuate locating the p | position of the corner: |
| A-13 & M-13 N80°E 56.3 S48°E 52.3 S85°E 79.42 N51°E 85.2 | fonument with 1/2" iron roo 4' to N&T in N. Side 3" Eln 5' to N&T in N. Side 8" Elm 2' to N&T in N. Side 7" Ceo 9' to N&T in SE Side 6" W. rsonite post 1' SW | Ratified by Pedar P.A. 345 - 199 | eer Group 90 Kalkaska Count 1414-99 | * # 1 MAVEAN LAG |
| Signed by Orange | . M. Mal. | | Date 12/3 | A 1999 |
| Surveyor's Michigan License No | | | | |
| 3019487 Page: 1 of 1 RS, JAN. 28, 1971 12/23/1999 10:56A REVISED JAN., 198: REMON REVISED OCT., 1991 Kalkaska County Joan Hall, Register LB: 6 PG: 43 | | | | |