MAR 2 1 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATED 7 JAN'S 1 PM 2: 44

Filing Requirement of Act 74, Mich. P.A. 1970

VAT VACVA	1 sector los	Corner Code ≠≠	REG OF DEEDS	
KALKASKA (County)	_ Located In:	Corner Code -++	A REPORTED	
1996 REMONUMENTATION	061 - 611	D-7		
. Public Land Survey	T 26N R 6W	• • •		
	T R		·	
	T R		•	
2. Property Controlling	S T R			
in Section	S T R			
3. Miscellaneous	S T R		Register of Deeds Stamp & File Num	ber
Property in Sec.	S R			
Lot No, Rec	corded Plat			
Private Claims				KLM
			2 - 6 5 1 - 3 2 -	
			3 + + + + + + + + + + + + + + + + + + +	
DIACHT MANDIED		0o+ 1 06	4 7 8 9 10 11-	12
EUGENE FARRIER	in a field survey on	19 90	lionari 5	++
io hereby certify that under requi	conformance with regulations a	nd rules therefore as required	in the	
urrent manual of survey instruct	tions of the United States Depa	rtment of the Interior, Bureau o	f Land 7	
lanagement or by a decree of a C bove were in conformance with	Court of Law and/or that the com the rules of the Michigan Board	er points mentioned in lines 3, 4 of Land Surveyors or by a Decr	ee of a 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
ourt of Law; established, re-	established, monumented, re-	monumented, recovered, fou	nd as	
xpressed below:			10 30 29 23 27 26	25
OTE: Not more than 4 cor	ners, all in the same town a	nd range, may be recorded		
on this certificate.	•		12 31 32 33 34 35	-136
Description of original mo	onument and accessories ar	nd/or subsequent restoratio	n:	
•				
D-07 cor common	to Sec. 17 & 20	, TZON-KOW, ULIV Doct 1/UFIm N57	E 23, 13"Sugar S24.5W 8.	≥((
08-12-1879 E.M	Mosher. Co. Surve	vor. used corner	, no accessories.	3 1/2
07-19-1901, W.S	Merrill. Co.Sur	veyor, used corn	er, no accessories.	3/1/
09-21-1972, LCR	C Liber 1 pg 89.		•	₹, Ø
04-01-1975, N.F	Parker, fd well	point. Liber 1	pg.651 of Survey.	温 别
04-01-1975, LCR	RC Liber 1 pg. 35	0.	<u>ق</u>	1990 Kalkaska
09-18-1975, LCR	C Liber 1 pg. 36	4-A.	7.66 a 5. Garage	8: W
11-06-1975, H.L	Flunarty, id 1"	pipe, Liber i p	g. 766 of Survey.	·하/1/
recorded in Lib	er 3, Pg. 127 of	Survey #0567, Id		Ω Ω
06-07-1991. E.D	Farrier. Survey	#7691. fd well	point, w/ accessories. 💃	P.A. 34 Chairm
•	•	•		₹ 5
B. Description of corner evid	dence found and/or method	applied in restoring or rees	stablishing comer:	-
D-07 cor commor	n to Sec. 17 & 20	, T26N-R6W, Oliv	er Township	
Found 1 1/4" We	ell point w/ acce	ssories. Pulled	& Set 5/8" x 18" re-rod w/	
Brass cap 1' Sc	outh of centerlin	e of Mecum Road	& 18' East of centerline o	f
Sohlaf Road (Pri	ivate), Also 1' E	last of fence Occ	. to 1' North & 1' West of	
centerline of C	overnead Power to	od & accented the	. witnesses were found. The above monument as a	ie
careful and fai	ithful perpetuati	on of the positi	on of the original corner.	
	F F	F	,	
			·	
Description of monument	for corner and accessories	established to perpetuate	ocating the position of the corner:	
	to Sec. 17 & 20			
Found 1 1/4" we	ll point w/ acce	ssories. Pulled	& Set 5/8" x 18" re-rod W/	
Brass cap 1' So	outh of centerlin	e of Mecum Road	& 18' East of centerline \circ	T
Sohlaf Road(Pri	.vate), Also 1' E	ast of fence Occ	. to 1' North & 1' West of	
	verhead Power to		A STATE OF THE STA	
Set nail & tag	NOSW Power Pole,	33.09'.	HANGE OF MICHIGAN	
Set nail & tag	N42E 10" R. Pine S67E 28" Maple,	85.35/	W 6	
Set nail & tag	South service Po	le, 32.36'.	S * EUGENE D. * 3 FARRIER * 3	
out mark a tay		a, _ =	PROFESSIONAL 15	
•			SURVEYOR NO.	
igned by king mu	There are	•	24594	\ - O ~
	//	Date	The April 19 Control of the Control	
ırveyor's Michigan License I	No. 24594		FORM APPROVED BY MANUELY THE SHAND OF LAND SURVEYORS.	
	.		REVISED	MAY 14, 1975 ED JAN., 1983
	TIRED 5 D	ACE 171		