MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T 26 NR 6 W

		Kai ka ska	COUNTY
DESCRIPTION OF CORN	ER Section corn	er common to Secti	ons 15-16-21-22
DESCRIPTION OF CORNE	R MONUMENT	"_pipe_with_4"_bra	ss_cap
WITNESSES TO CORNEL	R	·	
	6" Cedar	- N37E -	42½ links
	24" Elm	- s47E -	75 links
	10" Maple	- s50 W -	89 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored by Forestry Division survey crew while making a partial resurvey of this township. Established corner by double proportionate measurement, using original corners $\frac{1}{2}$ mile north and $\frac{1}{2}$ mile south, and established corners I mile east and west. Falls about 10 north of centerline of E-W county road. All government evidence gone in road construction.

Corner was placed and witnessed 9/23/59.

SURVEYOR'S SEAL

SIGNED LAND SURVEYOR

DATE 9/25/59_