MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_26_ NR__6 Y __

	Kalkaska	COUNTY
DESCRIPTION OF CORN	ER 1/4 corner common to Sections 15 &	16
DESCRIPTION OF CORNE	R MONUMENT 1" pipe, with 4" bra	88 Cap
WITNESSES TO CORNER	3	
	6" Cedar - N30E - 45	links
	8" Cedar N50W 9_	linka
·		
		•
DESCRIPTION IN DETAIL AS	TO HOW CORNER WAS LOCATED AND	IDENTIFIED OR

This corner was found by Forestry Division survey crew while making a partial resurvey of this township. Set corner from what we conclude to be the NE government BT. This is a 9" Tamarack, down and partially rotted at the buff, having both faces and scribed 1/4 S and NBT. Appears to have grown 60 years after marking, by ring count, and was 120 years old when it stopped growing. Found a small stake point when digging at corner. A possible site for SW government BT. Can find no record of subsequent survey.

Corner was placed and witnessed December 4, 1957.

SURVEYOR'S SEAL

SIGNED LEWELL Delling
REGISTERED LAND SURVEYOR

DATE 9-4-59