

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 26 NR. 6 W. . . .

Kalkaska COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 19-20-29-30

DESCRIPTION OF CORNER MONUMENT Left 1" pipe in place

WITNESSES TO CORNER


7" Poplar - N80E - 70 links

Corner fence post - S55W - 65½ links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a partial resurvey of this township. Found 1" pipe in center-line of N-S county road, in line with old township grade east and between lane fences west. All government evidence gone but was considered best available evidence of proper position for corner. Used for control of survey east.

Corner was witnessed September 2, 1959.



SIGNED *Kenneth J. Oetting*  
REGISTERED LAND SURVEYOR

DATE 9/4/59