MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T 26 NR 6 W

			-	2	al'este	COI	YTML
DESCRIPTION	OF	CORNER	Section_Corner	common to	Sections 2	,3,34 <u>0</u> 35	
DESCRIPTION	OF	CORNER	MONUMENT_1	Pipe vita	4" Brasa ca	p	
WITTNESSES	то	CORNER	14° Thite Pin	e_= N 74 T	97 Linka		
			6 * Cedar + 5	3 E = 29_1	inks		
				· 			
							-

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this Township. One original B.T. still in place, down, in good condition.

Corner was placed and witnessed June 11, 1952.

SURVEYORS SEAL

SIGNED LAND SURVEYOR

DATE 12/4/32