

KALAMAZOO ✓

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 26 N. R. 6 E. W.	A-2
2. PROPERTY CONTROLLING IN SECTION 6	T. 26 N. R. 6 E. W.	Code 3 Code 10
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. R. E. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on 11-10-72 19__, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19__, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- A-2 Recovered old irons per Merrill Survey dated 1904.
- Code 3 Established corner per Standard B.L.M. instructions.
- Code 10 Established corner per Standard B.L.M. instructions.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-2	Code 3	Code 10
Fd. buried broken iron & strapiron & small stones Added DNR Mon.	Set 1"x5' pipe & Cedar post w/loc. tag.	Set 1"x5' pipe & Cedar post w/loc tag.
9" tw bl. Cherry N24E 53.2'	12" Hemlock N77E 19.9'	16" Cedar N35E 7.6'
5" Ironwood S60E 13.0'	9" Maple S10E 15.3'	14" Cedar N83W 24.5'
7" Maple S19E 18.7'	10" Hemlock S80W 12.5'	10" Y. Birch S 4E 40.2'
N-S Rand. Due W 65.4'	N-S Rand. Due W 98'	10" Y. Birch S36W 27.8'
		N-S Rand. Due W 32.7'


SIGNED BY Carl F. Roser DATE 1-11-73

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR



SURVEYOR'S MICHIGAN REGISTRATION NO. _____