## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T 26 NR 6 W

		K	lai kaska	COUNTY
DESCRIPTION OF CORNER	Section corn	er com	mon to Sect	tions 15-16-21-22
DESCRIPTION OF CORNER	MONUMENT	<u>"_pipe</u>	with 4" b	rass_cap
WITNESSES TO CORNER	<b></b> -		· ·	
	6" Cedar		N37E -	42½ Links
	24" Elm	<b>60</b>	s47E -	75 links
	10" Maple		\$50 <b>W</b> -	89 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored by Forestry Division survey crew while making a partial resurvey of this township. Established corner by double proportionate measurement, using original corners is mile north and is mile south, and established corners is mile east and west. Falls about 10 north of centerline of E-W county road. All government evidence gone in road construction.

Corner was placed and witnessed 9/23/59.

SURVEYOR'S SEAL

SIGNED LAND SURVEYOR

DATE 9/25/59\_