## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T\_ % NR 6 #\_\_

		KelkekeCOUNTY
DESCRIPTION	OF CORNER	Section Corner common to Sections 10,11,14,15
DESCRIPTION	OF CORNER	MONUMENT_1 Pipo with At Bress cap
WITTNESSES	TO CORNER	8 Cefer - West - 9 Make
		_ 12"_Cefar_= 5 2 B = 13_Links
DESCRIPTION IN	DETAIL AS T	O HOW CORNER WAS LOCATED AND IDENTIFIED OR
This pertial resurve condition.	corner was for ay of this To	and by Forestry Division survey crow, while moking a waship. One original B.T. still in place, in good

SURVEYORS SEAL

Corner was placed end witnessed May 16, 1952.

SIGNED LAND SURVEYOR

REGISTERED LAND SURVEYOR