## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T\_ 26 NR 6 #\_\_

DESCRIPTION OF CORNER Section Corner common to Sections 10,11,14,15	
DESCRIPTION OF CORNER MONUMENT Fig. with At Breas sep	
WITTNESSES TO CORNER _ 5 Color - Test - 9 Links	
_ 12" Cedar = 5 2 E = 13 Links	
DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.	
This corner was found by Ferestry Division survey crew, while making a partial resurvey of this Township. One original B.T. still in place, in good condition.	
Corner was placed and witnessed New 16, 1952.	

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATE 12/4/52

\_\_\_\_\_Kalkaka \_\_\_\_ COUNTY