LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Kalkaska (County)	Located In Cor	rner Code #		
1. Public Land Survey	T <u>26N</u> R <u>6W</u>	M10		
2. Property Controlling in Section3. Miscellaneous	T <u>26N</u> R <u>5W</u> S T R S T R	A10		
Property in Section	S T R R S T R R		Register of Deeds Stamp & File Number	<u>r</u>
4. Lot No:	Recorded Plat:	·	A B C D E F G H I J K L N	м
5. Private Claims:			2 6 5 4 3 2	-
I, <u>Craig W. McVean</u> , in a field survey on <u>Aug. 18</u> , 20 <u>09</u> do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			3	
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.		range, may	10 30 29 28 27 26 25 11 11 12 31 32 33 34 35 36 13	-
A. Description of original monument and accessories and/or subsequent restoration:				
1) Hemloo 2) Hemloo North 1.18 - 1913 – Fa Set Temp - 1939 – M Retraced - 1978 – LO	LO – J. Mullett – Set ¼ post k 16" S28°W 11 L. k 8" N30°W 38 L. 6 Ch Manistee River 1.00 C. – SW. krgo Eng. – No US evidence . ¼ post only Schaaf – GLO Book Margin Notes Twp. Line. Nothing noted at this corner. CRC L. 2, p. 131 & Consumers Power Co Co, Sheet 8 & 9 – D. A. Ankrom – Set rel y on line.	4) 5" 5) 24 6) Tr o. Drawing	' Maple S75°W 21.41' ' Maple N46°W 27.14' 4" R. Pine S55°E 68.42' riple Maple 6" Ave. N17°E 50.97'	
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:				
M10 & A10 – Standard ¼ Corner common to Sec. 25, T26N, R6W and Sec. 30, T26N, R5W – Fd. ½" x 24" rebar per D. A. Ankrom. No GLO evidence. Measured North 102'± (78' – GLO) to Top of Bank of Manistee River coarse SW. ½" rebar accepted as a careful and faithful reestablishment of the position of the original corner.				
C. Description of monu	ment for corner and accessories establi	shed to perpetuate lo	ocating the position of the corner:	
Set Oranç N16°E 51 S57°E 68 S76°W 21	½" x 24" rebar with stamped 4" DNR Alge Carsonite Post 1' North .28' to set N & T in E. side 11" Tri. R. Ma .50' to set N & T in SW side 26" R. Pine .57' to set N & T in N. side 12" R. Maple '.09' to set N & T in SE side 12" R. Maple	aple (#6) (#5) e (#3)	CRAIG W. McVEAN PROFESSIONA SURVEYOR No. 39088	r YOR
Signed by:	www. Me Ven	Date:	11/23/2009	