## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Ear parpara in	Filing Requi	rement of Act 74, Mich.	P.A. 1970
For corners in  KALKASKA (County)	Located in:	Corner Code #	SURVEY & REMONUMENTATION
1998 REMONUMENTATION  1. Public Land Survey	T_26N R_8W TR T R	_E-7	FEB 2 2 1999
3. Miscellaneous S	T R T R T R T R		SECTION  Register of Deeds Stamp & File Number
4. Lot No, Recorded I	Plat		Авсреғеніјкь
5. Private Claims			1
I, EUGENE FABRIER, in a field survey on October 29, 1998_c hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner poin mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore a required in the current manual of survey instructions of the United States Department of the Interior Bureau of Land Management or by a decree of a Court of Law and /or that the corner poin mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented recovered, found as expressed below:			98_ do
NOTE: Not more than 2 corners, all in to on this certificate.	he same town and range, n	nay be recorded	11
(2.64') 1902, 1907, Sec. Sub. & Parcel Su 1948, Parcel Survey by (unknown) 5-172, J. Wilcox, Cert. of Survey, r 9-15-72, P. Perla, Cert. of Survey, r 12-12-73, L. Czubak, Cert. of Survey, 9-18-78, C.F. Roser, fd. 1/2" iron 8 8-19-81, E. Farrier, Cert. of Survey, 7-15-85, N. DeYoung, Cert. of Survey, 7-18-86, E. Farrier, Cert. of Survey, 12-13-88, E. Farrier, Cert. of Survey,	Cankin D.S.; set post a crewy by W.S. Merrill CS Co. Survey Bk. Pg. 54; rec. in Lib. 1, Pg. 15 fd. nail, rec. in Lib. 1, Pg. 486 fd. 1/2" iron & cap #12 cap, LCRC Lib. 2, Pg. 16. 1/2" iron, Lib. 2, Pg. 16. 1/2" iron, Lib. 2, Pg. 16. 1/2" iron, Lib. 2, Pg. 16. 1/2" iron & cap, Lib. 170 cap	(8W, Boardman Township of corner; Beech 12", S33 i., FB # 4, Pg. 67 & FB # stone at corner.  g. 176 i. (226, rec. in Lib. 1, Pg. 64 125 g. 710	<sup>o</sup> W, 15 Lks. (9.90'); Beech 14", N53°E, 4 Lks. 22, Pg. 141, notes stone at corner.
Pulled & set 5/8" X 18" re-rod w/ bit No G.L.O. witnesses were found.	, 17, 20 & 21, T26N-R 026 in centerline of 4 v rass cap in mon. box	8W, Boardman Township vay road int. (as rec. in LC	
C. Description of monument for corner E-7: Sec. Car. Common to Secs. 16 Fd. & accepted 1/2" iron & cap #12 S45°E, 56.71' - Power pole, set nail S20°E, 63.23' - 14" Maple, set nail S42°W, 64.03' - Power pole, set nail N70°E, 97.97' - Wood guard post (1) Signed by Michigan License No. 24594	, <u>17, 20 &amp; 21, T26N-B;</u> 026 in centerline of 4 v il & washer & washer ail & washer	8W, Boardman Township vay road int. Pulled & set	5/8" X 18" re-rod w/ brass cap in mon. box.  of Michola Strate Community Com

## "A" Continued

E7: Sec. Cor. Common to Secs. 16, 17, 20 & 21, T26N-R8W, Boardman Township 12-5-89, E. Farrier, Cert. of Survey 5-12-92, E. Farrier, Cert. of Survey 2-17-93, E. Farrier, Liber 4, Pg. 9, Cert. of Survey 8-9-94, E. Farrier, Fd. 1/2" iron, Cert. of Survey 6-5-98, E. Farrier, Cert. of Survey

## SURVEY & REMONUMENTATION

FEB 2 2 1999

SECTION