## SURVEY & REMONUMENTATION

FEB 1 3 1998

**SECTION** 

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	· · · · · · · · · · · · · · · · · · ·	······································	I	
KALKASKA	Located In:	Corner Code #		
1997 REMONUMENTATION  1. Public Land Survey	T_26N R_8W T R T R T R	<u>I-11</u>		
2. Property Controlling S_ in Section S_ 3. Miscellaneous S_ Property in Sec. S_	T		Register of Deed	s Stamp & File Number
4. Lot No, Recorded	Plat		— ABCDE	rg H I J K Ł M
5. Private Claims			1 1 1 1	4 - 3 - 2 - 1 -
I, FUGENE FARRIER  do hereby state that under requirer mentioned in lines 1 and 2 above required in the current manual of surv Bureau of Land Management or by mentioned in lines 3, 4 and 5 above Land Surveyors or by a Decree of	ments of P.A. 74, Michig were in conformance wit vey instructions of the Unit a decree of a Court of were in conformance wit	pan P.A. of 1970, the corner point h regulations and rules theroforo ted States Department of the Interion Law and /or that the corner point the the rules of the Michigan Board	as 7	9101112
recovered, found as expressed below:		nstieu, re-establistieu, monumente		28 27 26 25
NOTE: Not more than 2 corners, all in	the same town and range	, may be recorded	11 12 31 32 3	3 34 35 36
on this certificate.			13	
A. Description of original monum I-11: Section Cor. Common to Section 1852, GLO resurvey, 12" Sugar, 01-11-1898, Co. Surveyor, used 1902, W.S. Merrill Co. Surveyor, 10-20-1981, Granger Eng. Inc., fo 05-01-1990, Gourdie Fraser & as B. Description of corner evidence I-11: Section Cor. Common to Section 1/2" x 18" rebar 1.5' West of witnesses were fd. The Kalkaska of the original corner.	c. 26, 27, 34 & 35, T2 14" Beech N2 1/2E, 28 cor. for road work, no a pine stake, w/accessor d. 1/2" bar, w/accessor soc., fd. 1/2" rerod, w/ e found and/or method c. 26, 27, 34 & 35, T2 f C.L. Creighton Rd., Pu	26N-88W, Boardman Township accessories y ries, Lib. 2, Pg. 680 accessories, Lib. 3, Pg. 366 applied in restoring or reestablis 26N-88W, Boardman Township alled & replaced with 5/8" x 18"	shing corner:	FUGENE D. FARRIER PROFESSIONAL SURVEYOR NO. 24594 G. D. Box. No GLO evidence of the position
C. Description of monument for L-11: Section Cor. Common to Ser Fd. 1/2" x 18" rebar 1.5' West of Set nail & tag N41E, 8" R. Pine 6 Fd. Spike S45E, 20" Maple 48.24 Set nail S52W, P. Pole 41.75' N87W, survey marker post 26.36	c. 26, 27, 34 & 35, T2 f C.L. Creighton Rd., Pu 1.70'	26N-R8W, Boardman Township	rebar w/brass cap in mor  County	
Signed by Lugare	ano	Date	2-3-98	
Surveyor's Michigan License No.	24594	Date .		щ

