## SURVEY & REMONUMENTATION

FEB 1 3 1998

## **SECTION**

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in		1		
KALKASKA	Located In:	Corner Code #		
1997 REMONUMENTATION  1. Public Land Survey	T_26N R.8W TR T R	_M-1.1		
in Section S_	T R T R T R T R T R		Register of Deeds Stamp 8	k File Number
4. Lot No, Recorded	Plat		л в с р в ғ д н	IJKLM
5. Private Claims	:		1 2 3	21-
I, FUGENE FARRIER do hereby state that under requirenmentioned in lines 1 and 2 above required in the current manual of surv	nents of P.A. 74, Michigar were in conformance with	n P.A. of 1970, the corner points regulations and rules therefore as	4 7 8 9 10 5 6 18 17 i6 15 7	11-12
Bureau of Land Management or by mentioned in lines 3, 4 and 5 above Land Surveyors or by a Decree of recovered, found as expressed below:	a decree of a Court of La were in conformance with a Court of Law; establis	aw and /or that the corner points the rules of the Michigan Board of hed, re-established, monumented,	8 19 20 21 22 9 10 30 29 28 27 11	23 24
NOTE: Not more than 2 corners, all in on this certificate.	the same town and range, i	nay be recorded	12 31 32 33 34	35-36-
A. Description of original monum M-11: Sec. Cor. Common to Sec. 1852, GLO resurvey, set post, 18 04-27-1901, W.S. Merrill Co. Sur 05-20-1981, Farrier Surveying, LC 05-20-1981, Farrier Surveying, Cr. 11-17-1981, N. DeYoung, Cert. S 05-28-1987, Farrier Surveying, LC 05-30-1987, Farrier Surveying, Cr. B. Description of corner evidence M-11: Sec. Cor. Common to Sec. Fd. 1/2" iron 1' West of C.L. Puff The Kalkaska Co. Peer group apprint	25 & 36, T26N-R8W, Be Hemlock S45W, 36, 2 veyor, stone cor., no acc CR, fd. Iron raised w/nail, ert. Survey, fd. Iron raise Survey, fd. 5/8" rod, w/ac CR, fd 1/2" iron, w/acces ert. Survey, fd. 1/2" iron, ac found and/or method ac 25 & 36, T26N-R8W, Be er Rd., pulled & replaced	oardman Township 4" Hemlock N12W, 14 dessories W/accessories, Lib 2, Pg. 292 d w/nail, w/accessories dessories dessories dessories, Lib. 2, Pg. 323 dessories, Lib. 2, Pg. 323 dessories, Lib. 2, Pg. 323 dessories dess	ap in mon. box. No GLO witne	D. R. SINAL OF STANDARD SSES WERE Fd.
M-11: Sec. Cor. Common to Sec. Fd. 1/2" iron 1' West of C.L. Puffed. Nail S77W, P.Pole, 32.77' Fd. Nail N68E, 5" W. Pine, 51.10 Fd. N89W, 1/2" iron #24594, 33 Fd. S05W, conc. mon., 211.70' (	25 & 36, T26N-R8W, Bo er Rd., pulled & replaced , .00'	with 5/8" x 18" rebar, w/brass of Ratified P.A. 34 Chairm	ap in mon. box.  1 by Peer Group  5-1990 Kalkaska County  an Sugar Survey  1-29-98	
Signed by Surveyor's Michigan License No.	24594	Date	<u>-3-98</u>	
	3004 Page: 02/04/	1886 FORM APPROVED BY 1 of 1 98 11:22f	MICHIGAN STATE BOARD OF PROFESSIONAL SUR P	VEYORS, JAN. 28, 1971 REVISED MAY 14,1976 REVISED JAN., 1983 REVISED OCT., 1996