MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

	1. <u>20</u> R. K. <u>0</u>	Kalkasi	ka COUNTY
DESCRIPTION OF CORNER _	Section corner common to Sec	tions 17-18-19-2	0
CORNER MONUMENT	Drove 1/2 x 12" Iron bar to	surface of black	top
DATE MONUMENT PLACED AN	D WITHESSED <u>8/28/67</u>		
WITHESSES TO CORNER	••		
N	8 R. Pine	S 40 B	51.9 \$
17	6" S. Maple	S 60 W	167.3
CRCLE CORNER REGISTERED	AND		- The second

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored during a survey of Section 17. Set corner at proportionate measurement between 1/4 line fences 1/2 mile east and 1/2 mile west, at county surveyor's record distance from section corner south. This places corner about 2° north of centerline of road, and about 2 rods west of ROW fence north. Previous corner of record was marked by a stone, which we could not recover.

SURVEYOR'S SEAL

SIGNED Kuully Delleug DATE 9/20/67
REGISTERED LAND SURVEYOR \$10068