MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

	1. <u>ZO</u> <u>O</u>		
		Kalk	aska COUNTY
DESCRIPTION OF CORNER	Section corner common to Sect	ions 7-8-17-18	
CORNER MONUMENT	Set Cons. Dept. Mon.		
DATE MONUMENT PLACED AND	WITNESSED <u>8/28/67</u>		
WITHESSES TO CORNER			
	7" J. Pine	N 38 E	57•3°
17	6" Twin R. Pine	N 47 W	57.8 *
CIRCLE CORNER REGISTERED	AND		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored by proportionate measurement between corners one mile E-W-S and 1/2 mile north. Unable to locate anything for a previous corner. This point fits streams east and north, and checks good for distance all directions. Fence corner is about 19° S and 17° east, but can find no indication this was established according to survey.

SURVEYOR'S SEAL

SIGNED LEWILL Solling DATE 9/20/67
REGISTERED LAND SURVEYOR \$10068