MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_26_NR_4_W_ T 27 NR 8 W

		Kelkaska	COUNTY
DESCRIPTION	OF CORNER	1/4_Corner batween_Sections 6 & 31	
DESCRIPTION	OF CORNER	MONUMENT_132 Pipe with concrete	bese
WITTNESSES	TO CORNER	12* White Dak - N 34 W - 44 Links	
		9" Red QakN_22 E = 52_Links	_,
		6# Red Pine = 8 7 W = 70 Links	
			·

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner had been previously located and perpetuated by Marcus Scheef, Registered Land Surveyor. Burned over land, no original evidence remaining.

Corner was witnessed April 11, 1951.

SURVEYORS SEAL

SIGNED Ser C. Ser Suffer DATE 1/21/52 -