

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T 26 NR 8 W
T 26 NR 9 W
T 27 NR 8 W
T 27 NR 9 W

Kalkaska COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 6, 1, 31, 36

DESCRIPTION OF CORNER MONUMENT 1 1/2" Pipe with concrete base

WITNESSES TO CORNER 14" Red Pine - S 27 W - 150 Links

14" Red Pine - S 33 E - 134 Links

14" Red Oak - N 50 E - 57 Links

12" White Oak - N 52 W - 89 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner had been previously located and perpetuated by Marcus Schaaf, Registered Land Surveyor. Two original B.T.'s still in place, badly rotted.

Corner was witnessed April 11, 1951.

SURVEYORS SEAL

SIGNED Gene C. DeWaters DATE 1/21/52
REGISTERED LAND SURVEYOR