LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR COR	NERS OF -:	LOCATED	IN:	CORNER	CODE NUMBER			
1. PUBLI	C LAND SURVEY_	т. 26	N. 8 W.	C-1;D-1	E-2(E-3)			÷
2. PROPI	RTY CONTROLLING IN SECTION	,T	N. E. W.		·			
3. MISCE PROPE	LLANEOUS RTY IN SECTION		N. 8., R. <u>8</u> ₩. 6.57.	**657.1	3-S. of E-2 Sec.5, Cor.			
4. LOT N	0,	RECORDED PLAT	Code 1	4.				
	TE CLAIMS				<u> </u>		DEEDS STAMP AND)
ī	Carl F. Ro	oser	do hereby ce	ertify that und	der requirements	of P.A. 74, Mic	chigan P.A. of 19	70,
re-establis and rules Bureau o and 5 abo as expres	shed, monumented therefore as requi- f Land Manageme ove were, in a field	l in lines 1 and 2 and 1, re-monumented, ired in the current or by a decree of survey on Apriconformance with the survey of the	bove were, in a recovered or resmanual of surve a court of law. 11, 1978	field survey of stored as exp y instructions Furthermore 19, four	on March 2 pressed below and sof the United e, that the corner on the corner of the covered, recovered, respectively.	1 d in conforman States Departmer points ment stored, establish	19 <u>78</u> , establish nee with regulati nent of the Inter ioned in lines 3 ned or re-establisl	ed, ons ior, , 4 hed
XXXXXX	Zokikyk kok kokok kyk	XXXXXXXXXXXXXX	XXXXXXXXXXXXX	ON X KANKANK X Y	KKKKKKK			
C. (co	w/5, 6'' 18'' 8''	R.Pine S6 R.Pine S2 Ced.Post w/L	(buried); ra d w/RLS Cap. 9°E 36.2 6°E 60.0 6°E 36.4		Drove 5/8"X 6" R.Pine 9" R.Pine 7" R.Pine Set Ced.Pos in Ctr. of	N28°W N61°W S67°W t w/Loc.Tag	37.8 26.2 29.0 g Due W. 33'	
					. 11:1:			
C-1 Recove D-1 Fd. & E-2 Re-est E-3 Fd. M. Corner	red M. Schaar accepted Schaab. 1/4 Cor. Schaaf monum of record (19	widence found and, f monument, be aaf monument; on line betweent, buried, 951). Cor. of S 1/	uried in int for 1/4 cor. een Sec. Cor in southly w	ersection Fits Se ener's to N wheel trace	n of fire la ec. corners N. & S. and ck of E-W tr	ne trail ro to E & W, C at pro-rate ail road.	OK. ed distancé i Previous Dej	to U.S. pt.
C. Desc	ription of monume	nt for corner and a	accessories establ	ished to perp	etuate locating th	ne position of th	ne corner:	
re-rod w/R. 5" R.Pine 7" R.Pine 7" W.Pine	Mon.;Replace L.S. Cap (Bu: N45°E 3 N63°W 4	0.54 8.7	5/8"X36" Re (buried 0.5 6" Oak 17" Oak 10" Cherry Set Ced.Pos	e-rod w/R. 5) N23°W S66°E S18°W st w/Loc.?	39.3 62.7 37.6 Tag S33'	10" W.Pine 9" J.Pine 10" R.Pine Ctr. N-S T	S75°E 4 N54°W 4 S41°W 5 rail E. 2' <u>+</u> post w/Loc.t	3.0 9.8 4.2
			Cor. falls of E-W Trai	in S.Whee il Rd.	el Track	11111111111111111111111111111111111111	111,	
SIGNED	By Carl	7. Por	es 9-10	8-78	_ DATE	THE OF WI	CHINA	
		REGISTRATION			2	G CARL F. ROSE LAND	R Z	
		ED STATES AGE				SURVEYOND.	DR 6	
SIGNED	BY	CHIEF OF SU			DATE	FAED LAND	SURVIENT	
APPROV		D BY			DATE_	"Harmy		
		MICH	IIGAN REGIBTERED LA	IND SURVEYOR		(SEA BOARDMAN TO	DWNSHIP	
SURVEY	OR'S MICHIGAN	N REGISTRATION	S NO			KALKASKA CO	JUN I I	