MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

	1. <u>20</u> N. K. <u>8</u>	<u>W</u>		
		<u>Kalk</u> s	Kalkaska COUNTY	
DESCRIPTION OF CORNER	Section corner common to Sect	ions 7_8_17_18		
CORNER MONUMENT	Set Cons. Dept. Mon.			
DATE MONUMENT PLACED AND	WITNESSED <u>8/28/67</u>			
WITHESSES TO CORNER	•			
N	7" J. Pine	N 38 E	57•3°	
17	6" Twin R. Pine	N 47 W	57.81	
CIRCLE CORNER REGISTERED	AND			

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored by proportionate measurement between corners one mile E-WLS and 1/2 mile north. Unable to locate anything for a previous corner. This point fits streams east and north, and checks good for distance all directions. Fence corner is about 19° S and 17° east, but can find no indication this was established according to survey.