LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 26 N. S., R. 8 E. W.	E-6; E-7; F-6
2. PROPERTY CONTROLLING IN SECTION 16	T. 26 N. S., R. 8 E. W.	8; 9
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on April 10, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. (continued)

8			9		
Set 5/8X36" Re-Rod & Cedar post w/Loc. tag.			Set 5/8X36" Re-Rod & Cedar Post w/Loc. Tag		
7" R.Pine	N05°E	42.45	3" W. Pine	S05°E	64.1
22" R.Pine	S52°E	57.24	8" W.Pine	S27°W	52.8
15" Oak	S65°W	51.62	7" W.Pine	N42°W	28.9
Fd. 1/2" Re-Rod					
	S02-19-50E	13.34			
In Old Fn. South (down) ±					

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

E-6 Fd. 1/2" rod, buried, in approx. ctr. of N-S gravel county road, in line with cementery fence to W. Previous Dept. Cor. of record (1967).

E-7 Fd. Ir. with RLS Cap in Ctr. E-W black top road, gravel rds. to N&S.

F-6 Fd. rod with RLS Cap, at intersection of onequarter lines, for Ctr. of Sec. 16. Rod by Perla-Stout, L.Czubek, RLS. Cor. is in line with ctr. of gravel rd. South.

8 Established 1/8 Corner per Std. B.L.M. instructions.

9 Established 1/8 Corner per Std. B.L.M. instructions.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-6			E-7			F-6		
Fd. 1/2" rod; raised with 3/4"X18" pipe.			Fd. RLS Cap in B.Top rd., could not read number.			Fd. 1/2" Rod w/Cap		
14" W.Pine	S44°E	38.05	9" Maple	S12°E	63.06	Fd. 1/2" Ir. Rod Buried 0.5'~		
21" W.Pine	N25°E	84.00	9" Maple	N24°E	107.43		Due S	27.11
17" R.Pine	N37°W	58.90	Ctr. N-S rd's			26" Ir. Wood	S47°W	64.49
Set Cedar Post w/Loc. Tag		W. 33'		Due W	6'±	30" Maple	Due W	22.27
						23" Maple	S56°E	21.85
						Ctr. of rd. to	W S.	27'±

SIGNED BY Carl F. Roser 9-18-78 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN — CARL F. ROSER — LAND SURVEYOR — No. 12028 — REGISTERED LAND SURVEYOR (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

BOARDMAN TOWNSHIP
KALKASKA COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET