LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 26 N. S., R. 8 E. W.	F-4; G-4; G-5
2. PROPERTY CONTROLLING IN SECTION 9	T. 26 N. S., R. 8 E. W.	8; 9
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on May 3, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. (continued)

8			9		
Set 1"X48" pipe w/plastic RLS Cap & Ced. post w/loc.tag			Drove 5/8"X42" re-rod w/plastic cap & set Ced.post w/Loc.Tag		
24" Cedar	N51°W	28.3	12" W.Pine	N34°E	33.3
11" Cedar	S58°W	27.0	12" Cedar	N22°W	48.2
6" Cedar	N41°E	10.6	8" Cedar	S45°W	63.6

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

F-4 Established Ctr. of Sec. 9 at intersection of 1/4 lines.

G-4 Re-established 1/4 Corner equidistant & on line between Sec. Corners to N&S.

G-5 Recovered pointed stk. bottom, 0.5' deep in muck , from remains of U.S.B.T. stumps SE&NW (cedars) and Merrills W.Pine stp.,N61°E, 25.1' (still standing) & remains of his Tam. stp. NW; Merrills data is in his U.S. Note Bk.#19, dated Oct. 22, 1908.

8 Established 1/8 Corner per standard B.L.M. instructions.

9 Established 1/8 corner per standard B.L.M. instructions.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-4			G-4			G-5		
Set 1"X5' Pipe w/R.L.S. plastic cap & Ced.Post w/Loc. Tag.			Set DNR Mon. & Ced.Post			Set DNR Mon. & Ced.Post		
14" Cedar	S06°W	34.4	27" Triple Cedar	S65°W	22.2	7" Cedar	S08°W	57.7
12" Cedar	S59°W	36.1	12" Cedar	S17°E	52.4	10" Maple	N54°W	43.6
12" Cedar	N68°E	6.3	13" Maple	N56°W	31.8	10" Cedar	N25°W	33.9
			5' Wide Creek	Due S	30'±	20" W.Pine	N07°E	109.2
			Cor. on N-S Random & Ran.W			N-S Rand	Due E	1.2'

SIGNED BY Carl F. Roser 9-18-78 DATE _____

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

BOARDMAN TOWNHSIP
KALKASKA COUNTY

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET