LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF-:	LOCATED IN-:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 26 N. S., R. 8 E. W.	E-1;F-1;G-1;G-2
2. PROPERTY CONTROLLING IN SECTION	T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on October 26, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

~~Description of original monument and accessories and subsequent restoration~~

G-2 B. (continued) at N. end of overgrown fire lane from South.

G-2

Fd. Schaaf Mon. & replaced with
DNR Mon. & Ced.Post

10"	R.Pine	S25°W	46.9
9"	W.Pine	S53°W	24.7
11"	R.Pine	N57°W	34.9
N-S	Rand.	Due E.	26'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

E-1 Fd. 1 1/4" Short Nipple in conc. block (buried in intersection of fire lanes N-S-W; old Schaff monument. Fd. Schaaf Pits 33' NW&33' SE & U.S.B.T. stump. Y.Pine 18", N40°E, 21.8'.

F-1 Restored 1/4 cor.from USBT remains: W.P. stump, S33°W, 15.8'; Y.P stump, N27°E, 10.6';

both stumps showing lower faces. Corner falls in old overgrown E-W RR Grade,E-W Random 2.2'N.

G-1 Restored Govt. cor. from U.S.B.T. remains, 10"Y.Pine stump showing partial lower face, N19°W, 31.0'. Corner fits U.S.L.T. remains (Y.Pine stump), 13 chains ± South. Removed old L.E.S. post, that was 4'±N.

G-2 Recovered Schaaf Mon. from Schaaf Pits 33'-NE & 33'-SW and remains of USBT, (Y.P.stump, N68°W,15.8').Fits remains of USLT (Hem.Tree&Stump remains) 10 chains N.+. Cor. is (continued)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Above

E-1

Fd. 1 1/4" short Nipple in conc. blk. (Schaaf Mon.) & replaced w/5/8"X36" re-rod w/R.L.S. cap

18"	R.Pine	S59°E 51.86
9"	R.Pine	S 8°W 24.57
3"	R.Pine	S74°W 41.87

Set cedar post w/Loc.Tag N 25'

F-1

Set DNR Mon. & Ced.Post

3"	Maple Cluster	N 9°W	37.9
15"	R.Pine	S83°E	35.5
12"	R.Pine	S57°W	75.1

G-1

Set D.N.R. Mon.&Ced.Post

8"	R.Pine	N59°E	20.0
11"	R.Pine	S 3°W	36.8
11"	R.Pine	N89°W	58.0

SIGNED BY Carl F. Roser 9-18-78 DATE _____

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR (SEAL) No. 12028 REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

BOARDMAN TOWNSHIP
KALKASKA COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET