MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_27_ NR_5_W__

			Kelkaska	COUNTY
DESCRIPTION	OF	CORNER	1/4 Corner between Sections 22 & 23	
DESCRIPTION	OF	CORNER	MONUMENT_14 Pipe with 4" There cap .	·
WITTNESSES	то	CORNER	_8"_Aspen = % 20 % = 37 Links	
			_8" Aspen - N 59 E - 10 Links	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner had been previously located by Marcus Schaaf, Registered Land Surveyor, from original B.T.'s.

Corner was placed and witnessed February 23, 1951.

SURVEYORS SEAL

SIGNED _ LIL DATE 3/21/51 _
REGISTERED LAND SURVEYOR