

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 27. NR. 6 W.

Kalkaska COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 27 & 28

DESCRIPTION OF CORNER MONUMENT 4" Cedar post at corner in stream
Set pipe with brass cap for witness corner 10 links north
WITNESSES TO CORNER of true corner.

NBTs to Witness Corner

7" Cedar	-	S72E	-	56 links
7" Cedar	-	N36W	-	37 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a partial resurvey of this township. Found original SE BT in place, but rotting, with good face and scribed 1/4 S. Found original stake point in stream.

Corner was placed and witnessed May 15, 1956

SURVEYORS SEAL

SIGNED

Billy D. Buckles
REGISTERED LAND SURVEYOR

DATE 5/17/56