

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 27. NR. 6. W. . .

Kalkaska COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 33 and 34

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER

6" Cedar	-	S58E	-	32 1/2 links
8" Cedar	-	S38W	-	62 1/2 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a resurvey of this township. Found a very old squared post at corner, obviously set by proportionate measure between section corners. Considered acceptable since Balsam government BTs cannot be identified.

Corner was placed and witnessed 10-20-59.

SURVEYORS SEAL

SIGNED *Kenneth J. Ostling*
REGISTERED LAND SURVEYOR

DATE 10/21/59