

Kalknska ✓

# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

| FOR CORNERS OF--:                          | LOCATED IN--:                         | CORNER CODE NUMBER     |
|--|---------------------------------------|------------------------|
| 1. PUBLIC LAND SURVEY _____                | T. <u>27</u> N. S., R. <u>6</u> E. W. | <u>A-11 &amp; B-11</u> |
| 2. PROPERTY CONTROLLING IN SECTION _____   | , T. _____ N. S., R. _____ E. W.      | _____                  |
| 3. MISCELLANEOUS PROPERTY IN SECTION _____ | , T. _____ N. S., R. _____ E. W.      | _____                  |
| 4. LOT NO. _____, RECORDED PLAT _____      |                                       |                        |
| 5. PRIVATE CLAIMS _____                    |                                       |                        |

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on 11-9 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_ 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration: