



8 0 5 0 0 1 3
Tx:4034718
2/3/2016 4:05:00 PM

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: <u>Kalkaska</u> (County)	Located In	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S <u>15</u> T <u>27N</u> R <u>7W</u> S _____ T _____ R _____	12, 14
3. Miscellaneous Property in Section	S _____ T _____ R _____ S _____ T _____ R _____	_____
4. Lot No: _____	Recorded Plat: _____	
5. Private Claims: _____		

DOCUMENT # 3128801
STATE OF MICHIGAN
KALKASKA COUNTY
RECORDED: 03/03/2016 4:13 PM
PAGES: 1
RECORDING FEES: 14.00
JOANN DEGRAAF REGISTER OF DEEDS
BK: 4 PG: 9

Register of Deeds Stamp & File Number

I, Joshua R. Davidson, in a field survey on October 1, 2014 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

12 – CS 1/16 corner section 15

14 – S 1/16 corner common to sections 14 & 15

1973 – Certificate of Survey – L. 1, P. 801 – James H. Granger, PS #16041 – Set Mon.

1973 – Certificate of Survey – L. 1, P. 801 – James H. Granger, PS #16041 – Set Mon.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

12 – CS 1/16 corner section 15

14 – S 1/16 corner common to sections 14 & 15

Found 4" round concrete monument and accepted as the best available evidence of the position of the corner.

Found 4" round concrete monument and accepted as the best available evidence of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

12 – 4" round concrete monument.

14 – 4" round concrete monument.

Set blue post with location tag 1' Northeast.

Set blue post with location tag 1' Northwest.

N70°E 27.21' to set nail & tag in E. side 14" R. Maple in clump of 5
S70°E 31.21' to set nail & tag in N. side 11" Twin Birch
S37°W 37.71' to set nail & tag in W. side 10" Oak
N56°W 42.72' to set nail & tag in NE. side 9" R. Maple in clump of 4

N58°E 9.85' to set nail & tag in SE. side 3" Fir
S64°E 2.24' to set nail & tag in NE. side 12" R. Maple
S10°W 97.46' to set nail & tag in E. side 22" W. Pine
S34°W 41.50' to set nail & tag in SW. side 3" W. Pine

Signed by:

Joshua R. Davidson

Date: March 3, 2016

Surveyor's Michigan License No.: 46659

