MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

	T. <u>27</u> N. R. <u>8</u>	<u>W</u>	
		Kalka	aska COUNTY
DESCRIPTION OF CORNER	1/4 corner common to Sections	19-20	,
CORNER MONUMENT	Set Cons. Dept. Mon.		
DATE MONUMENT PLACED AND	WITNESSED 10/4/67		
WITNESSES TO CORNER			· · · · · · · · · · · · · · · · · · ·
	- 7" W. Pine	N 36 W	6.71
20	7" W. Pine	S 20 W	11.81
CIRCLE CORNER REGISTERED			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by proportionate measurement between section corners during a survey of Section 20. Could not locate a previous corner after extensive search. Checks south edge of Darby Lake very well. Falls on west edge of NLS fireline.

SURVEYOR'S SEAL

SIGNED Lewell & Ostling DATE 10/4/67
REGISTERED LAND SURVEYOR #20068