

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION



# LAND CORNER RECORD

T. 27 N.R. 8 W


Kalkaska COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 17-18

CORNER MONUMENT Set 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 4-20-67

WITNESSES TO CORNER.....



10" R. Oak N 21 E 15.9'


7" H. Maple N 70 W 11.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this township. Found pipe in concrete monument at corner, as previously restored by Marcus Schaaf, R.L.S., during a 1934 survey of this township. Cannot identify anything for U.S.B.T.'s.



SURVEYOR'S SEAL

SIGNED \_\_\_\_\_ DATE 4-25-67

REGISTERED LAND SURVEYOR #10068