## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

	T. 27 N.R. 1. N.R.	Te.	ilkaska rand Traverse COUNTY
DESCRIPTION OF CORNER	1/4 corner common to Secti	ons 7 - 12	
CORNER MONUMENT	Set 1" pipe with 4" alumin	num cap below sun	face
DATE MONUMENT PLACED AND WITNESSES TO CORNER	D WITNESSED 4-13-67		
	24" H. Maple	S 25 E	24.7 <sup>t</sup>
77	5N R. Pine	N 40 W	56.71
CIRCLE CORNER REGISTERED			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this township. Recovered corner, marked with a stone with cross on top, as established or identified by Merrill in 1909 survey. Falls in line with roads east and west and fence line south. Checks very well for line and distance to good corner north.

SURVEYOR'S SEAL

SIGNED		DATE	4-25-67
	BECKETERER I AND BURYEVAR NA A A A		