

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 27 N.R. 8 W


Kalkaska COUNTY

DESCRIPTION OF CORNER Sec. Corner common to Sections 14-15-22-23

CORNER MONUMENT Set 1" pipe with 4" Alum. Cap below surface

DATE MONUMENT PLACED AND WITNESSED 4-26-67

WITNESSES TO CORNER.....



8" J. Pine N 68 E 67.9°

7" J. Pine N 35 W 51.7°

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a survey in this township. Found 3/4" pipe at corner which we conclude perpetuates corner as established by Merrill in early 1900 survey. Remains of his NBT in place SE.

SURVEYOR'S SEAL

SIGNED _____ DATE 4-26-67
REGISTERED LAND SURVEYOR #10068