

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION



# LAND CORNER RECORD

T. 27 N. R. 8W


Kalkaska COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 13-14-23-24

CORNER MONUMENT Set 1" pipe with 4" Alum. cap

DATE MONUMENT PLACED AND WITNESSED 4-27-67

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

14" R. Pine N 44 E 95.0°

6" J. Pine N 44 W 111.8°

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a survey in this township.

Found 3/4" pipe at centerline intersection of road, established by unknown. Fits survey pattern north and west, and was considered best available evidence as to proper location for corner.

SURVEYOR'S SEAL

SIGNED \_\_\_\_\_ DATE 4-27-67

REGISTERED LAND SURVEYOR #10068