

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 27 N.R. 8 W


Kalkaska COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 7-18

CORNER MONUMENT Set 1" pipe with 4" aluminum cap below surface

DATE MONUMENT PLACED AND WITNESSED 4-7-67

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

5" W. Pine N 32 W 82.3'

10" R. Pine S 68 W 38.1'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a retracement in this township. Found pipe in concrete monument at corner, in firelines E-W and South. Previously established in 1934 survey by Marcus Schaaf, R.L.S. Nothing left for U.S. evidence.

SURVEYOR'S SEAL

SIGNED _____ DATE 4-24-67
REGISTERED LAND SURVEYOR #10068