LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 28 N., R. 7 W.	L-9
2. PROPERTY CONTROLLING IN SECTION 25	T. 28 N., R. 7 W.	4; 5; 8; 9
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on May 10, 1976, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19__, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. (continued)

8

Set 1¼"x2' rod (buried in sand road)

17" Oak	N67°E	61.93
20" Oak	N45°W	54.08
16" Oak	S57°W	74.54
Fd. 1¼" pipe	S88°30'40"E	12.85
Set cedar post w/loc. tag		
	Due W	33'

9

Set ½"x48" iron bar & ced. post w/loc. tag

6" Maple	S55°E	16.3
14" Maple	S52°W	36.6
9" Maple	N84°W	48.6
6" Maple	N29°W	53.4

NW cor. of wood frame cottage on cement blocks S46°E 29.1

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

L-9 Found 1½" pipe that fits C.P.C. Survey of south line of Sec. 24. At an approximate position of N35°E 7'± from fd. pipe, would be ¼ corner position by B.L.Caukin survey of Sec. 25 dated 1919 from two of his witnesses.

4 Established center of NW¼ of Sec. 25 per standard B.L.M. instructions.

5 1/16 corner-drove 1¼"x24" iron rod buried in gravel entrance road (in curve) to well site to east; per standard B.L.M. instructions.

8 Established 1/16 corner per standard B.L.M. instructions.

9 Established 1/16 corner per standard B.L.M. instructions.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-9

Fd. 1½" pipe & set cedar post w/loc. tag

10" Cherry	S19°E	91.73
15" Cherry	S61°W	107.15
36" Maple	N77°W	129.40
Ctr. E-W sand road (in curve)		
	Due N	33'±

4

Set ½"x5/8"x5' bar & cedar post w/loc. tag

5" Cherry	N62°E	79.6
6" Maple	N27°W	49.9
20" Cherry	N80°W	59.4
8" Cherry	S05°E	84.4

5

Drove 1¼"x2' rod (buried)

8" Maple	N77°W	62.0
10" Cherry	S62°W	61.1
8" Cherry	S73°E	54.1
Set cedar post w/loc. tag		
	Due E	33'

SIGNED BY Carl F. Roser DATE 10-31-77

STATE OF MICHIGAN (SEAL) CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

RAPID RIVER TOWNSHIP
KALKASKA COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET