STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		<u>KALKASKA</u>	COUNTY
	-	T <u>28 N</u>	R <u>5 W</u>
DESCRIPTION OF CORNER	1/4 CORNER COMMON TO SECT	TIONS 7-8	
CORNER MONUMENT	SET DEPT. MON.		
DATE MONUMENT PLACED AND	WITNESSED 6-30-69		
WITNESSES TO CORNER	•		
N	7" Oak	S 05 E	49.3'
7	6" Oak	N 84 E	66.8'
	W. Pine Str	N 79 E	48.1' (B.L.C
	Old_NBT = N	o. N 27 E lo record.	75.3'
CIRCLE CORNER REGISTER	ŒD		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

THIS CORNER WAS FOUND DURING A RETRACEMENT IN THIS TOWNSHIP. FOUND POST BOTTOM AND IRON BAR AT CORNER AS ESTABLISHED BY B. L. CAUKINS IN 1919 SURVEY. MANY CORNERS IN SECTIONS 5, 6, 7, 8 HAD TO BE ESTABLISHED BECAUSE OF FRAUDULENT OR ERRONEOUS GOVERNMENT SURVEY IN THIS AREA, AS INDICATED BY MEANDERS OF STARAVATION LAKE. MOST EARLY DEVELOPMENT OF THIS AREA BELIEVED TO BE REFERENCED TO CAUKINS CORNERS, AND NOTHING MORE DECISIVE IS AVAILABLE. SECTION 7 SUBDIVISION BY CAUKINS BASED ON THIS LOCATION. THE MEANDER CORNER ON NORTH SIDE EAGLE LAKE, BY B.L.C. WAS ALSO RECOVERED, FROM WITNESSES, AT WATER'S EDGE, AND MARKED WITH A 1 1/4" pipe.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

🟏 DATE

7_25_60

REGISTERED LAND SURVEYOR 10069

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing