

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 28 N. R. 5 W


Kalkaska COUNTY

DESCRIPTION OF CORNER SEC. CORNER COMMON TO SECTIONS 19-20-29-30

CORNER MONUMENT LEFT 1 1/2" PIPE IN PLACE

DATE MONUMENT PLACED AND WITNESSED AUGUST 1968

WITNESSES TO CORNER.....



7" MAPLE S 43 W 50.8'

7" HEMLOCK S 22 E 70.1'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

THIS CORNER WAS FOUND DURING A RETRACEMENT IN THIS TOWNSHIP. FOUND 1 1/2" PIPE AT INTERSECTION OF ROADS, PROBABLY AS ESTABLISHED OR FOUND IN SCHAAF SURVEY. APPEARS TO BE IN SAME POSITION AS CAUKINS SURVEY DESCRIBES IT. BEST AVAILABLE EVIDENCE.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Ostling* DATE 9/5/68  
REGISTERED LAND SURVEYOR #10068